

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2024

Submitted Date:

07/10/2024

Document Number:

696306501**FIELD INSPECTION FORM**Loc ID 418098 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418101	WELL	TA	05/01/2019	OW	123-31827	Antelope 23-18	TA
418102	WELL	TA	04/25/2019	OW	123-31828	Antelope 14-18	TA
418111	WELL	TA	04/26/2019	OW	123-31829	Antelope 24-18	TA
418113	WELL	TA	04/26/2019	OW	123-31830	Antelope 18C	TA
418209	WELL	TA	04/26/2019	OW	123-31852	Antelope 13-18	TA

General Comment:

This is a Well PAD and Tank Battery Inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	All 4 reamaining Wellhead Signs have faded no longer visible; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	08/09/2024
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 4		
Comment:	Appeare to be plumbed to surface		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 4		

Comment:	TA Wellheads		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	400 BBLs	STEEL AST		40.395830,-104.369280	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 418101 Type: WELL API Number: 123-31827 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 05.01.2019

MIT - 07.01.2021

Form 6A - 403213997 with a Plug Due Date of 12.31.2029

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 418102 Type: WELL API Number: 123-31828 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Well appears to have been Plugged and Abandoned recently per Form 42 PA - 403807358 with a MIRU Date of 05.29.2024. Form 6N - 403753877 on File.

Form 27 - 403770673 dated 05.06.2024 on File

Well has not yet been Cut and Capped

No Form 6S on File yet

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 418111 Type: WELL API Number: 123-31829 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 04.26.2019

MIT - 03.29.2021

Form 6A - 403213997 with a Plug Due Date of 12.31.2029

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 418113 Type: WELL API Number: 123-31830 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 04.26.2019

MIT - 03.29.2021

Form 6A - 403213997 with a Plug Due Date of 12.31.2029

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 418209 Type: WELL API Number: 123-31852 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 04.26.2019

MIT - 11.11.2020

Form 6A - 403213997 with a Plug Due Date of 12.31.2029

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine Field Inspection . Wellhead Signs have faded no longer visible	petrie	07/10/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403849977	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617299
696306502	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617290