

# Inspection Photos

Loc: 386457

Operator: AMOCO PRODUCTION COMPANY

Inspection Date: 7/12/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south along the access road.





## Inspection Photos



**Photo 2.** Facing northeast along the road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:334513 | Date: 7/12/2024



## Inspection Photos



**Photo 3.** Further along the road back to the south traveling to the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:334513 | Date: 7/12/2024



## Inspection Photos



**Photo 4.** Facing southeast near the location. This area has rock rip along the road side.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:334513 | Date: 7/12/2024



## Inspection Photos



**Photo 5.** Facing southeast at the well pad location.





## Inspection Photos



**Photo 6.** Facing toward the fill slope of the location. There has been additional work performed for stormwater control. The wattles have been replaced and hydromulch was applied.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:334513 | Date: 7/12/2024



## Inspection Photos



**Photo 7.** Facing northeast toward the cut slope.





## Inspection Photos



**Photo 8. Facing toward the south side of the location.** There has been additional work performed for stormwater control. The wattles have been replaced and hydromulch was applied.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:334513 | Date: 7/12/2024



## Inspection Photos



**Photo 9.** Facing north along the fill slope of the location. There are filter wattles installed along the slope.





## Inspection Photos



**Photo 10.** Facing down the fill slope to the west.





## Inspection Photos



**Photo 11.** Center of the fill slope north.





## Inspection Photos



**Photo 12.** North side of the fill slope facing down to the southwest..





## Inspection Photos



**Photo 13.** North side of the location facing south.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:334513 | Date: 7/12/2024



## Inspection Photos



**Photo 14.** Facing south along the canyon drainage used to access the location bottom. There are noxious weeds (Canada thistle) that need to be controlled.





## Inspection Photos



**Photo 15.** Facing east at the bottom of the slope of the well pad.





## Inspection Photos



**Photo 16.** Facing east toward the location standing across the canyon.

