

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 2906 From entrance to location



Photo # 2907 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 2908 Location



Photo # 2909 Location

# Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 2910 Location

Photo # 2911 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 2912 Location

Photo # 2913 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 2914 Location



Photo # 2915 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 2916 Debris