

Inspection Photos

07/18/2024

Operator: ANSCHUTZ EXPLORATION CORP -
3104

Location ID: 430927

Inspection Doc: 696205993

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



Photo 1: Photos taken from the interim areas on the south end of the Location. Photos examples showing compaction issues remain apparent; compaction alleviation (cross-ripping to a minimum of 18") has not been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



Photo 2: Photo taken from the access road on the east end of the Location. See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



Photo 3: Photo left shows anchor on the northeast end of the Location- anchor has been marked. Photo right shows areas of the southeastern anchor; anchor appears to have been buried and has not been marked.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



Photo 4: Fluids within honeypot.

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



Photo 5: Photo shows secondary containment BMP remains inadequate to contain a spill or release. Photo right shows fluids have spilled within containment.

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



Photo 6: Photo shows fluids have spilled from the compressor equipment.

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



Photo 7: Spills on Location have not been cleaned.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



Photo 9: Photo taken from the topsoil stockpile. Stockpile is predominantly Undesirable Plant Species. Topsoil has also not been replaced during interim reclamation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources