

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2024

Submitted Date:

07/17/2024

Document Number:

697009760

FIELD INSPECTION FORM

Loc ID 329835 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------|
| , | | ECMCInspections@Oxy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 250111 | WELL | SI | 01/01/2019 | OW | 123-17914 | HSR-GEORGE 1-6 | SI |

General Comment:

This is a routine inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator personnel on location at the time of this field inspection.

LocationOverall Good: ☒**Signs/Marker:**

Type WELLHEAD

Comment: [Sign is not posted at well, see attached photo.](#)Corrective Action: [Install sign to comply with Rule 605.d.](#)Date: 09/20/2024**Emergency Contact Number:**

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: [Panel](#)

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

1

Comment: [Bradenhead valve is exposed at surface.](#)

Corrective Action:

Date:

Type: Flow Line

1

Comment: [OOSLAT](#)

Corrective Action:

Date:

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |

Comment: [Tank battery #448394](#)

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type Capacity Permeability (Wall) Permeability (Base) Maintenance

| | | | | | |
|--------------------|--|--|--|--|-------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 250111 | Type: | WELL | API Number: | 123-17914 | Status: | SI | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned | | | | | | | | | |
| Reminder: | | | | | | | | | |
| Comment: Form 6A #403108165 | | | | | | | | | |
| Corrective Action: | | | | | | | | | |
| Date: | | | | | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: 05/17/2023 | | | | | | | | | |
| Annual Brhd Completed? No | | | | | | | | | |
| Last Brhd Test Results | | | | | | | | | |
| Initial Surf Csg Pressure: 1 | | | | | | | | | |
| Fluid Type: None | | | | | | | | | |
| End Surf Csg Pressure: -- | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | | | | |
| Date: | | | | | | | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

| Comment | User | Date |
|--|-----------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Wednesday 7/17/2024 at approximately 10:40 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the KMG HSR George 1-6 location #329835 in Weld County, Colorado.</p> <p>While there, I observed that the wellhead sign was not posted. During this inspection the following possible compliance issues were observed: Rule 605.d. with a corrective action date of 9/20/2024.</p> <p>A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p> | petersont | 07/17/2024 |

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403857594 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6625671 |
| 697009761 | Photo | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6625668 |