

Interim Reclamation and Stormwater Inspection

Date: 07/23/2024

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 440776

Inspection Document #: 708201421

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 1. Northern interim areas appear to have been reclaimed with evidence of drill rows and crimped mulch.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 2. Northwest interim areas, facing north. See comments in Photo 1.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 3. West interim areas, facing northwest. See comments in Photo 1.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 4. Southwest interim areas, facing west. See comments in Photo 1.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 5. Stained soil within SW portion of tank battery.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 6. Tank labels have been replaced, west side of tank battery.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 7. Unused equipment observed west of tank battery.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 8. Tank labels have been replaced, east side of tank battery.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 9. NFPA Placards and labels have been replaced.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 10. Unmarked riser/unused equipment, south of compressor station, remains on location.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 11. Unused equipment south of compressor station does not appear to have been removed or returned to service.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 12. Unused equipment within compressor station does not appear to have been removed or returned to service.



Photo 13. Stained soil does not appear to have been properly disposed of.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776



Photo 14. Unused equipment does not appear to have been removed or returned to service.

Inspection Photos
Location Name: Arellano 10-L Facility
Location ID: 440776




Photo 15. Unused equipment/unmarked riser and stained soil does not appear to have been removed or properly disposed of.