

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2024

Submitted Date:

07/24/2024

Document Number:

708302451

FIELD INSPECTION FORM

Loc ID 334415 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296553	WELL	PR	07/01/2018	GW	045-16074	BATTLEMENT MESA 26-22D	PR
296577	WELL	PR	06/01/2023	GW	045-16075	BATTLEMENT MESA 26-12B	PR
296579	WELL	SI	02/01/2024	GW	045-16076	BATTLEMENT MESA 26-12C	SI
296582	WELL	PR	09/01/2014	GW	045-16077	BATTLEMENT MESA 26-12D	PR
296586	WELL	SI	02/01/2024	GW	045-16078	BATTLEMENT MESA 26-13A	SI
296591	WELL	PR	07/01/2018	GW	045-16079	BATTLEMENT MESA 26-13B	PR
296594	WELL	PR	09/01/2017	GW	045-16080	BATTLEMENT MESA 26-13C	PR
296596	WELL	PR	09/01/2017	GW	045-16081	BATTLEMENT MESA 26-13D	PR
296603	WELL	PR	07/01/2018	GW	045-16082	BATTLEMENT MESA 26-14A	PR
296604	WELL	SI	05/01/2023	GW	045-16083	BATTLEMENT MESA 26-23A	SI
296605	WELL	PR	08/01/2020	GW	045-16084	BATTLEMENT MESA 26-23B	PR
296606	WELL	SI	04/01/2023	GW	045-16085	BATTLEMENT MESA 26-23C	SI
296607	WELL	SI	04/01/2023	GW	045-16086	BATTLEMENT MESA 26-22B	SI
296608	WELL	PR	09/14/2009	GW	045-16087	BATTLEMENT MESA 26-22C	PR

General Comment:

CECMC Inspection Report Summary

On 7/17/2024 at approximately 12:45, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, Battlement Mesa/26K-795 at Location ID #334415 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Open-ended heating lines at tank battery pose a wildlife entry hazard

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Delay in report submission due to technical issues. Any corrective action dates will be in effect from date of submission, not date of inspection.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	OTHER		
Comment:	Open-ended heating lines at tank battery pose a wildlife entry hazard.		
Corrective Action:	Secure wildlife entry hazards.	Date:	07/29/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Spill kit		
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 14		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 14		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	7	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities			
Facility ID: <u>296553</u>	Type: <u>WELL</u>	API Number: <u>045-16074</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>296577</u>	Type: <u>WELL</u>	API Number: <u>045-16075</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>296579</u>	Type: <u>WELL</u>	API Number: <u>045-16076</u>	Status: <u>SI</u> Insp. Status: <u>SI</u>
Idle Well			
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____		
Comment:	Last produced January 2024		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>296582</u>	Type: <u>WELL</u>	API Number: <u>045-16077</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>296586</u>	Type: <u>WELL</u>	API Number: <u>045-16078</u>	Status: <u>SI</u> Insp. Status: <u>SI</u>
Idle Well			
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____		
Comment:	Last produced January 2024		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>296591</u>	Type: <u>WELL</u>	API Number: <u>045-16079</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>296594</u>	Type: <u>WELL</u>	API Number: <u>045-16080</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296596 Type: WELL API Number: 045-16081 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296603 Type: WELL API Number: 045-16082 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296604 Type: WELL API Number: 045-16083 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced March 2024

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296605 Type: WELL API Number: 045-16084 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296606 Type: WELL API Number: 045-16085 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced March 2024

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296607 Type: WELL API Number: 045-16086 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced March 2024

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296608 Type: WELL API Number: 045-16087 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Ditches				
Gravel						
Compaction						
		Compaction				
		Gravel				
Berms						

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302452	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638189