

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2024

Submitted Date:

07/20/2024

Document Number:

708904217**FIELD INSPECTION FORM**Loc ID 323783 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: PO BOX 13550City: BAKERSFIELD State: CA Zip: 93389**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:22 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210798	WELL	PR	10/01/2023	GW	045-06556	MEAD 23-44-6S-94W	PR

General Comment:**CECMC Inspection Report Summary**

On 07/18/2024 at approximately 10:30 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad.
Location # 323783 in Garfield County Colorado.

Please refer to inspection 708901771 conducted on 09/22/2023, 2 of 3 previous corrective actions have been completed.
Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site & in close proximity to NSO Habitat area.
Location is approximately 240 yards from Beaver Creek & approximately 575 yards from the Colorado River.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Erosion & transport of sediment onto location with a CA date of 10/09/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Compressor engine oil tank		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/888-291-8588		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed wire		
	Barbed wire fence showing some signs of disrepair (SW corner of location)		

Corrective Action:				Date:	
Equipment:				corrective date	
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment: Marked Some deadman markers are insufficient height - All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.					
Corrective Action:				Date:	
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 0				
Comment: Well is not on plunger lift					
Corrective Action:				Date:	
Type: Compressor	# 1				
Comment:					
Corrective Action:				Date:	
Type: Other	# 1				
Comment: Fire extinguisher					
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment: Compressor engine oil tank					
Corrective Action:				Date:	
Type: Other	# 1				
Comment: Slug catcher					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment: No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.					
Corrective Action:				Date:	
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)	Compressor engine oil	
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		,

Comment:	Tank not equipped with telemetry			
Corrective Action:				Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Separate containment			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	210798	Type:	WELL	API Number:	045-06556	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well not on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in some areas
Other	Fail					Erosion & transport of sediment onto location
Berms						
		Gravel				Sparse
Compaction						Light compaction in some areas
		Compaction				

Comment: 1. Erosion & transport of sediment onto location/insufficient BMP's

Corrective Action: Comply with CECMC Stormwater rules

Date: 10/09/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Stormwater for corrective action & also refer to Housekeeping, Fencing & Equipment for comments.	smelserw	07/20/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403860230	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6632651
708904218	Inspection 708904217 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6632649
708904219	Inspection 708904217 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6632650