

Craig 2

Location 327437

Photo Log

Corrective Action:	Conduct maintenance on equipment, cleanup stained material. Per Rule 1002..(2).D and review self inspection processes
Description:	Stained soils at wellhead removed



Corrective Action:	Conduct maintenance on equipment, cleanup stained material. Per Rule 1002..(2).D and review self inspection processes
Description:	Stained soils at skim tank removed

