

# Work Completion Report

Contractor: Peerless

## JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
HSR-SANDBERG 2-6 TANK BATTERY	July	Armando Munoz	7/24/2024
Work Summary	Reclamation Type	Land Use	
We repaired deeps riling and ruts caused by erosion. Surface roughened and track packed with skid steer added roadbase and compacted.	Stormwater	Active Pad	
One-Call Number	Red Zone Rep	Red Zone Date	

## WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Stormwater Repairs	Normal	Yes	Location(s): HSR-SANDBERG 2-6 Notes: ECMC Corrective Action due 8/9/2024, please complete ASAP and submit completion report.


## COMPLETION DETAILS

Total Area Affected: **11,539 sq ft**  
Seed Mix: **None used**  
Crop Type: **Corn**  
Soil Type: **Clay Loam**  
Stabilization Date: **7/24/2024**  
Seeding Date:  
Mulch: **None**  
Straw Bales: **NA**  
Soil Amendment Type: **Roadbase**  
Soil Amendment Rate: **50 Tons\Acre**  
Imported Top Soil: **NA**  
Top Soil Source: **NA**  
General Notes:

PHOTOS

Photo Name: Site Map

Description:



**Photo Name: Pre-Completion**

Description:





**Photo Name: Post-Completion**

Description:



**Photo Name: HSR2**

Description:





**Photo Name: HSR3**

Description:



**Photo Name: HSR4**

Description:





**Photo Name: HSR5**

Description:





**Photo Name: HSR6**

Description:

