

Interim Reclamation and Stormwater Inspection

July 17, 2024

Operator: GMT EXPLORATION COMPANY LLC #10243

Location ID: 479197

Inspection Document #: 697505397

Elbert County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Marble-Redstone/Pad
Location ID: 479197



Photo 1. Photo taken from a wellhead, illustrating the Operator sign.



Photo 2. Photo taken along the western working pad surface, facing South. Photo illustrates the reclamation construction areas are in process of vegetation establishment.



Inspection Photos
Location Name: Marble-Redstone/Pad
Location ID: 479197



Photo 3. Photo taken along the western working pad surface, facing West. Photo illustrates the topsoil stockpile has been stabilized with an hybrid introduced/native grass mix.



Photo 4. Photo taken along the northwestern perimeter of location, facing West. See comment under Photo 2.

Inspection Photos
Location Name: Marble-Redstone/Pad
Location ID: 479197



Photo 5. Photo taken along the northwestern perimeter of location, facing Northwest. Photo illustrates a retention pond with a stabilized outlet.



Photo 6. Photo taken along the northwestern perimeter of location, facing North. Some rill erosion was observed along the slopes of the retention pond.

Inspection Photos

Location Name: Marble-Redstone/Pad

Location ID: 479197



Photo 7. Photo taken along the northern perimeter of location, facing East. Photo illustrates weedy, annual vegetation establishment on the topsoil stockpile. Note- there was some establishment of desirable species on the south-facing slope.



Photo 8. Photo taken along the northern perimeter of location, facing East. See comments under Photo 7.



Inspection Photos
Location Name: Marble-Redstone/Pad
Location ID: 479197



Photo 9. Photo taken along the northeastern working pad surface, facing West. Photo is an overview of the location.



Photo 10. Photo taken along the northeastern working pad surface, facing South. See comment under Photo 9.

Inspection Photos
Location Name: Marble-Redstone/Pad
Location ID: 479197



Photo 11. Photo taken along the southern production area, facing East. Photo illustrates wildlife protection devices (netting) are missing for secondary containment BMPs.



Photo 12. Photo taken along the southeastern perimeter of location, facing East. Photo illustrates the reclamation construction area is in process of vegetation establishment; however, there is a lack of desirable vegetation.

Inspection Photos
Location Name: Marble-Redstone/Pad
Location ID: 479197



Photo 13. Photo taken along the southern perimeter of location, facing West. See comments under Photo 12.



Photo 14. Photo taken along a portion of the access road west of the production facility, facing West. Photo illustrates a culvert in need of maintenance.

Inspection Photos
Location Name: Marble-Redstone/Pad
Location ID: 479197



Photo 15. Google Earth aerial imagery from 9/4/2023 illustrates the location and the northern portion of the access road.

