

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2024

Submitted Date:

08/01/2024

Document Number:

708904269

FIELD INSPECTION FORMLoc ID 335243 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

25 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211125	WELL	PR	12/22/1995	GW	045-06884	COOK RW 5-29	PR
256342	WELL	PR	10/27/1999	GW	045-07441	SAVAGE RWV 129-29	PR
295182	WELL	PR	02/20/2009	GW	045-15693	SAVAGE RWF 443-29	PR
295183	WELL	PR	10/19/2008	GW	045-15694	SAVAGE RWF 334-29R	PR
295184	WELL	PR	01/31/2009	GW	045-15695	SAVAGE RWF 434-29	PR
295185	WELL	PR	05/01/2014	GW	045-15696	SAVAGE RWF 34-29	PR
295186	WELL	PR	01/31/2009	GW	045-15697	SAVAGE RWF 533-29	PR
416355	WELL	PR	05/01/2014	GW	045-19254	SAVAGE RWF 433-29	PR
416356	WELL	PR	05/01/2022	GW	045-19255	SAVAGE RWF 33-29	PR
416360	WELL	PR	10/01/2011	GW	045-19256	SAVAGE RWF 444-29	PR
416361	WELL	PR	12/01/2022	GW	045-19257	SAVAGE RWF 543-29	PR
416363	WELL	PR	10/01/2011	GW	045-19258	SAVAGE RWF 344-29	PR

General Comment:

CECMC Inspection Report Summary

On 08/01/2024 at approximately 14:21 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RMV 129-29 Pad.

Location # 335243 in Garfield County Colorado.

Please refer to inspection 708901444 conducted on 08/21/2023, previous corrective action has been completed.

Location is within High Priority/Density/Black Bear Habitat areas & Bald Eagle Roost Site & in close proximity to NSO Habitat area & Bald Eagle Nest Site.

Location is approximately 244 yards from the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Open hole/wildlife & personnel hazard with a CA date of 08/08/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Split pad/remote location - Wellheads only, separator units & production tanks are located on the SAVAGE RU 28 Pad, location # 335291

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Open hole near wellhead/wildlife & personnel hazard 2nd smaller hole near another wellhead which is also a hazard		
Corrective Action:	Comply with CECMC wildlife & safety rules	Date:	08/08/2024
Type	OTHER		
Comment:	Small amount of staining near some wellheads		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 12		corrective date
------------------	------	--	-----------------

Comment:	RWF 34-29 & RWF 344-29 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible.			
	Remaining 10 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.			
Corrective Action:			Date:	
Type: Plunger Lift		# 11		
Comment:	COOK RW 5-29 well not on plunger lift			
	Remaining 11 wells all on plunger lift			
Corrective Action:			Date:	
<u>Venting:</u>				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
<u>Flaring:</u>				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities				
Facility ID:	211125	Type:	WELL	API Number: 045-06884 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well not on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	256342	Type:	WELL	API Number: 045-07441 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	295182	Type:	WELL	API Number: 045-15693 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	295183	Type:	WELL	API Number: 045-15694 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	295184	Type:	WELL	API Number: 045-15695 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	295185	Type:	WELL	API Number: 045-15696 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	295186	Type:	WELL	API Number: 045-15697 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	416355	Type:	WELL	API Number: 045-19254 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	416356	Type:	WELL
API Number:	045-19255	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	416360	Type:	WELL
API Number:	045-19256	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	416361	Type:	WELL
API Number:	045-19257	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	416363	Type:	WELL
API Number:	045-19258	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts				
Compaction						Light compaction
Gravel						Sparse to none in most areas
		Gravel				Sparse to none in sections
		Ditches				

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping for corrective action.	smelserw	08/01/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904270	Inspection 708904269 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649104
708904271	Inspection 708904269 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649105