

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403876890

Date Received:
08/05/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 7650
Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION
Address: 4900 COLLEGE BLVD
City: FARMINGTON State: NM Zip: 87402

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|----------------|--------------|----------------------------|
| Zach Stradling | 505-325-8874 | zstradling@bmgdrilling.com |

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000836
Inspection Date: 06/12/2024 FIR Submit Date: 06/21/2024 FIR Status:

Inspected Operator Information:

Company Name: BENSON-MONTIN-GREER DRILLING CORPORATION Company Number: 7650
Address: 4900 COLLEGE BLVD
City: FARMINGTON State: NM Zip: 87402

LOCATION - Location ID: 325388

Location Name: LA POSTA CANYON-N33N10W Number: 5NENE County:
Qtrqtr: NENE Sec: 5 Twp: 33N Range: 10W Meridian: N
Latitude: 37.137517 Longitude: -107.952021

FACILITY - API Number: 05-067-00 Facility ID: 325388

Facility Name: LA POSTA CANYON-N33N10W Number: 5NENE
Qtrqtr: NENE Sec: 5 Twp: 33N Range: 10W Meridian: N
Latitude: 37.137517 Longitude: -107.952021

CORRECTIVE ACTIONS:

1 CA# 196027

Corrective Action: Regrade/recontour access road per rule 1004a. Date: 07/31/2024

Response: CA COMPLETED Date of Completion: 07/24/2024

Operator Comment: The access road is at grade with surrounding ground. This area is an active pipeline ROW. HES harrowed, seeded and mulched the access road. Branches and sticks were placed across the road to deter use. The site and access road were showing good growth of native grasses.

ECMC Decision: _____

ECMC
Representative:

| |
|--|
| |
|--|

OPERATOR COMMENT AND SUBMITTAL

Comment: The access road is at grade with surrounding ground. This area is an active pipeline ROW. HES harrowed, seeded and mulched the access road. Branches and sticks were placed across the road to deter use. The site and access road were showing good growth of native grasses.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Zach Stradling

Signed: _____

Title: Vice President

Date: 8/5/2024 1:13:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| Document Number | Description |
|------------------------|--------------------------|
| 403876927 | Work summary w/ pictures |

Total Attach: 1 Files