

Final Reclamation and Stormwater Inspection

Date: 8/1/24

Operator: PDC Energy Inc - 69175

Location ID: 323503

Inspection Document #: 713900821

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Spaur 10-3
Location ID: 323503



Photo 1. The photo was taken at the entrance to the tank battery location facing Southeast. The photo illustrates erosion at the entrance to the tank battery.




Photo 2. The photo was taken at the tank battery location facing North. The photo illustrates the tank battery is dominated with crested wheatgrass and cheatgrass. However, there were some perennial grasses were observed germinating.

Inspection Photos
Location Name: Spaur 10-3
Location ID: 323503



Photo 3. The photo was taken at the tank battery location facing East. Refer to the comment for photo 2.

Photo 4. The photo was taken at the tank battery location facing South. Refer to the comment for photo 2.

Inspection Photos
Location Name: Spaur 10-3
Location ID: 323503



Photo 5. The photo was taken at the tank battery location facing West. Refer to the comment for photo 2.



Photo 6. The reference photo was taken near the tank battery location facing Southeast. Reference areas were dominated by sandberg bluegrass, rabbitbrush and yucca.

Inspection Photos
Location Name: Spaur 10-3
Location ID: 323503



Photo 7. The photo was taken at the well location facing North. The photo illustrates some growth of wheat with large areas bare soil and cereal rye throughout.



Photo 8. The photo was taken at the well location facing East. Refer to the comment for photo 7.

Inspection Photos
Location Name: Spaur 10-3
Location ID: 323503



Photo 9. The photo was taken at the well location facing South. Refer to the comment for photo 7.

Photo 10. The photo was taken at the well location facing West. Refer to the comment for photo 7.

Inspection Photos
Location Name: Spaur 10-3
Location ID: 323503



Photo 11. The photo was taken at the well location facing Southeast. The photo illustrates a frame of wood that appears to be located at the former wellhead.



Photo 12. The reference photo was taken at the well location facing Northwest. The photo illustrates reference areas are dominated with wheat.