

Well Site Inspection

Date:07/25/2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 333124

Inspection Document #: 708201440

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Nessu-Kinder 16
Location ID: 333124



Photo 1. Wellhead casing appears to have been repaired; no visible or auditory indications of venting equipment observed at the time of this inspection.

Inspection Photos
Location Name: Nessu-Kinder 16
Location ID: 333124



Photo 2. Pump jack is disassembled and unused equipment needs to be removed from the location or returned to service.

Inspection Photos
Location Name: Nessu-Kinder 16
Location ID: 333124



Photo 3. Undesirable vegetation and noxious weeds were observed throughout the location. It does not appear that undesirable/noxious vegetation has been managed for since the previous inspection.

Inspection Photos
Location Name: Nessu-Kinder 16
Location ID: 333124



Photo 4. Continued from Photo 3. CO List C Noxious Weed (canada thistle) observed on the south end of location.



Photo 5. Pump jack is disassembled and unused equipment needs to be removed from the location or returned to service.