

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Weeds



Weeds

KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310



Oily waste and stained soil



Debris

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Label illegible



Damaged and unusable equipment



**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Additional information required when replaced



Debris

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Equipment leak



Weeds

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Erosion and sediment migration




Erosion and sediment migration

KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310



Weeds. Relief risers missing caps



Calibration overdue.

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Location from Northwest corner



Location from Southwest corner

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Location from Southeast corner



Location from Northeast corner