

Inspection Photos

API: 043-06231

Operator: AUSCO PETROLEUM INC

Inspection Date: 8/5/2024



Inspection Photos



Photo 1. Facing toward the drainage crossing which has been washed out and has not been repaired. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 8/5/2024

Inspection Photos



Photo 2. View of culvert outlet shows displaced rock. Outlet protection will need to be reinstated. Previous corrective action was not completed.



Inspection Photos



Photo 3. Facing southwest toward the wellsite. There are undesirable weeds around the equipment that need to be controlled. The pupjack is unused equipment that needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 8/5/2024

Inspection Photos



Photo 4. Facing southwest toward the interim reclamation area. The perennial vegetation has not established and the straw wattle is displaced. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 8/5/2024

Inspection Photos



Photo 5. Facing northwest toward the interim reclamation area. The perennial vegetation has not established. This area will need weed control and reseeding. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 8/5/2024

Inspection Photos



Photo 7. Facing toward the pumpjack. The pumpjack is unused and needs to be removed. The fire extinguisher has fallen over.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 8/5/2024