

# Inspection Photos

API: 043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 8/5/2024



## Inspection Photos



**Photo 1.** Drone aerial photo facing northwest along the access road. There are some check dams where stormwater is going around the check dam. BMP maintenance is needed. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 043-06219 | Date: 8/5/2024



## Inspection Photos



**Photo 2.** Drone aerial photo facing north toward the wellsite location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API: 043-06219 | Date: 8/5/2024



## Inspection Photos



**Photo 3.** Drone aerial photo facing north toward the wellsite location. The degraded wattles still remain in the upper left at red arrow.





## Inspection Photos



**Photo 4.** Facing northwest. This well has been inactive for a long period of time. Equipment is unused and needs to be removed. There are weeds growing around the equipment which is a fire hazard.





## Inspection Photos



**Photo 5.** Facing east at the location. There is undesirable weeds, Russian thistle growing throughout this area by the equipment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API: 043-06219 | Date: 8/5/2024