

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2024

Submitted Date:

08/06/2024

Document Number:

713601272

FIELD INSPECTION FORM

Loc ID 429883 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|---------------------------|--------------------------------|---------|
| Harkins, Liz | 303-233-2232/719-429-4513 | Lharkins@austinexploration.com | |
| Hart, Tim | | thart@fremontpetroleum.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|----------------------|-------------|
| 429883 | LOCATION | AC | | | - | Pathfinder C 14-01 1 | RI |

General Comment:

This is a follow up of the previous inspections #713600187, #713600366.
The previous inspection corrective actions have not been completed.
See attached photos and additional details within this report.

LocationOverall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | This well is not producing and is temporarily abandoned. The pumpjack and tanks are unused equipment. All unused equipment must be removed. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 09/06/2024 |
| Type | WEEDS | | |
| Comment: | There were noxious weeds previously observed at the west side of the location in the sediment trap. There are undesirable weeds and vegetation growing by the equipment which is a fire hazard. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 08/15/2024 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| | | | | | | |
| <div>Comment: <div>There are displaced and degraded wattles that need to be repaired. There are rock check dams along the access road that need maintenance. The sediment trap at west side of the location has filled in with sediment. Previous corrective action was not completed.</div></div> | | | | | | |
| <div>Corrective Action: <div>Install or repair required BMPs per Rule 1002.f.(2)C</div></div> | | | | | | Date: |
| <div>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</div> | | | | | | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|-------------------|---|
| Document Num | Description | URL |
| 713601273 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6654507 |