

# Inspection Photos

Loc: 424805

Operator: **JAVERNICK OIL**

Inspection Date: 8/5/2024

County: FREMONT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest at the beginning of the access road. There are undesirable weeds along the access and the access road which has not been reclaimed.





## Inspection Photos



**Photo 2.** Facing south toward the location which has not been reclaimed per 1004 Rules.





## Inspection Photos



**Photo 3.** Facing northwest at the location. There are undesirable weeds throughout the location which is a fire hazard.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:424805 | Date: 8/5/2024



## Inspection Photos



**Photo 4.** Southeast corner of the location facing north along the fill slope. There are undesirable growing along the fill slope that need to be controlled. The location has not been recontoured. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:424805 | Date: 8/5/2024



## Inspection Photos



**Photo 5.** South side of the location facing west. There is new disturbance in this area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:424805 | Date: 8/5/2024



## Inspection Photos



**Photo 6.** Facing west toward the cut slope which is not stabilized. There is new disturbance in this area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:424805 | Date: 8/5/2024



## Inspection Photos



**Photo 7.** Facing southeast toward the location. The barbed wire fence is not maintained and wire is strung out at red arrow. Fence should be removed or repaired.

