

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2024

Submitted Date:

07/31/2024

Document Number:

699700388**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Heil, John \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
,		COGCCInspectionReports@terraep.com	TEP
Cholas, Nick		nick.cholas@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477727	PRODUCED WATER TRANSFER SYSTEM	CL	08/25/2020		-	PW_WestMammCreek	EI
487252	SPILL OR RELEASE	AC			-	TR 21-36-597 PW Transfer Line	EI

**General Comment:**

ECMC Environmental Inspection.



**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 100

Comment: See Initial Form 19 Doc #403845956 and Supplemental Form 19 Doc #403853321 for more information. ECMC staff John Heil and Nick Cholas conducted an Environmental Inspection of the spill/release area as well as the unknown tributary adjacent to Willow Creek. A detectable hydrocarbon odor was present around the spill/release area at time of inspection. A sheen was not present on the unknown tributary adjacent to Willow Creek as well as Willow Creek below the confluence of the two creeks.

Corrective Action: Operator shall comply with CAs on Mike Longworth Inspection 7/10/2024 Doc #701104046.

Date:

Reportable: YES

GPS: Lat 39.576900

Long -108.224350

Proximity to Surface Water:

Depth to Ground Water:

**Water Well Complaint:**

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

**Field Parameters:**

Sample Location:

Comment:

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403872890	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646806">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646806</a>
699700389	20240708 Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646799">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646799</a>