

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2024

Submitted Date:

07/31/2024

Document Number:

707801043

FIELD INSPECTION FORM

 Loc ID 316766 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
 ECMC Operator Number: 7125
 Name of Operator: BEEMAN OIL & GAS INC
 Address: 13635 E 104TH AVENUE STE 400
 City: COMMERCE CITY State: CO Zip: 80022
Contact Information:

Contact Name	Phone	Email	Comment
Stepp, Sarah		wcciassistant@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232758	WELL	PR	02/09/1991	OW	107-06173	PEOC-NVG 41-23H	PR

General Comment:**ECMC Inspection Report Summary**

On Wednesday 7/17/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Beaman PEOC-NVG-41-23H, at Location # 316766 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Random staining
2. Weeds on location
3. Random debris
4. Unused/stored equipment
5. Tank was actively venting from thief hatch

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Random weeds		
Corrective Action:	Remove weeds	Date:	08/26/2024
Type	OTHER		
Comment:	Random staining		
Corrective Action:	Remove and dispose of stained material	Date:	08/26/2024
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	08/09/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment and stored equipment on location		
Corrective Action:	Remove all unused and stored equipment. Keep location free of equipment not used on lease or provide proper and approved documentation for stored equipment.	Date:	08/26/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	Well head		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Unused equipment		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Propane tank		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES	
Comment:	Theif hatch was actively venting	
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition	Date: 08/09/2024

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 232758 Type: WELL API Number: 107-06173 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none
		Compaction				Light compaction in areas
Gravel						Sparse to none

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403872680	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646641
707801046	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646635
707801047	Video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646636