

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403874407

Date Received:

08/08/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Sanford, Eric [inspection@sginterests.com](mailto:inspection@sginterests.com)

[esanford@sginterests.com](mailto:esanford@sginterests.com)

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000980

Inspection Date: 07/24/2024

FIR Submit Date: 07/25/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

#### LOCATION - Location ID: 385883

Location Name: SHORT 33-9-N33N9W Number: 17SWNW County: \_\_\_\_\_

Qtrqr: SWN Sec: 17 Twp: 33N Range: 9W Meridian: N

Latitude: 37.106228 Longitude: -107.854148

#### FACILITY - API Number: 05-067- -00 Facility ID: 385883

Facility Name: SHORT 33-9-N33N9W Number: 17SWNW

Qtrqr: SWN Sec: 17 Twp: 33N Range: 9W Meridian: N

Latitude: 37.106228 Longitude: -107.854148

### CORRECTIVE ACTIONS:

1 CA# 196909

Corrective Action: Comply with rule 1003.f treat/remove weeds.

Date: 08/08/2024

Response: CA COMPLETED

Date of Completion: 11/12/1992

Operator

Comment:

Doc. No. 560674:

This May 15, 1998 letter from SG's consultants provides information that this location was a previously constructed and reclaimed well pad prior to SG's ownership of this lease.

Texas Oil and Gas, Corp. constructed the well pad in 1980 and abandoned the location in 1981.

SG initiated the process to permit a new well on this previously constructed and abandoned location in 1998. The only work SG conducted on this location was survey work, as shown in the photos in ECMC's database. SG conducted no ground disturbing work on this location. SG did not drill the Fruitland Coal well permitted in 1998.

In 2003, SG submitted an Abandoned Location Sundry Notice, showing that SG did not construct this location after permitting the well in 1998. This Sundry Notice was approved by COGCC with no Conditions of Approval. See attached Form 4 Short\_AL\_10/03/2003

Doc. No. 401589049:  
On 11/12/1992, COGCC conducted an inspection for the location and created a Field Inspection Report. This Field Inspection Report indicated a "Pass" for "Reclamation." See Doc. No. 401589049, page 10.

Doc. No. 401589050:  
COGCC again conducted and inspection in November of 2018 and issued Corrective Actions related to Rule 1004. In the FIR Resolution Form for this 2018 inspection, SG related the same information that is being again provided herein. SG additionally sought a Factual Review Request in this FIRR, related to the fact that SG conducted no physical work at this location. See Doc. No. 401589050.

Doc. No. 401589021:  
On 12/27/2019, COGCC approved a Form 4 Sundry related to the 2018 inspections and SG's responsive FIRR, stating, "Per communication with FIU Manager and Supervisor, passing form, SGI does not hold responsibility for AL location." See Doc. No. 401589021, page 5.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative: \_\_\_\_\_

**2** CA# 196910

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: \_\_\_\_\_

Response: CA COMPLETED \_\_\_\_\_

Date of Completion: 11/12/1992

Operator  
Comment:

Doc. No. 560674:  
This May 15, 1998 letter from SG's consultants provides information that this location was a previously constructed and reclaimed well pad prior to SG's ownership of this lease. Texas Oil and Gas, Corp. constructed the well pad in 1980 and abandoned the location in 1981.

SG initiated the process to permit a new well on this previously constructed and abandoned location in 1998. The only work SG conducted on this location was survey work, as shown in the photos in ECMC's database. SG conducted no ground disturbing work on this location. SG did not drill the Fruitland Coal well permitted in 1998.

In 2003, SG submitted an Abandoned Location Sundry Notice, showing that SG did not construct this location after permitting the well in 1998. This Sundry Notice was approved by COGCC with no Conditions of Approval. See attached Form 4 Short\_AL\_10/03/2003

Doc. No. 401589049:  
On 11/12/1992, COGCC conducted an inspection for the location and created a Field Inspection Report. This Field Inspection Report indicated a "Pass" for "Reclamation." See Doc. No. 401589049, page 10.

Doc. No. 401589050:  
COGCC again conducted and inspection in November of 2018 and issued Corrective Actions related to Rule 1004. In the FIR Resolution Form for this 2018 inspection, SG related the same information that is being again provided herein. SG additionally sought a Factual Review Request in this FIRR, related to the fact that SG conducted no physical work at this location. See Doc. No. 401589050.

Doc. No. 401589021:  
On 12/27/2019, COGCC approved a Form 4 Sundry related to the 2018 inspections and SG's responsive FIRR,

stating, "Per communication with FIU Manager and Supervisor, passing form, SGI does not hold responsibility for AL location." See Doc. No. 401589021, page 5.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: This is an abandoned location. SG did not build a well pad or drill on this location. A factual review request was previously completed and approved for this well stating SG does not hold responsibility for the abandoned location. The date of 11/12/1992 that was put in the CA's was from a previous operators actions that COGCC documents indicate this location was passed for reclamation, however SG did not complete this work as SG did not build a well pad on this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Arnett

Signed: \_\_\_\_\_

Title: Reg Permitting

Date: 8/8/2024 1:44:22 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403878538	Correspondence
403878540	Abandoned Location Sundry-Well pad not built
403878542	1992 FIR Pass Reclamation
403878547	2018 FIRR Factual Review Request
403878550	Approved FIRR-SG does not hold responsibility

Total Attach: 5 Files