

Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SESE

Location ID: 335776

Date: 8/1/2024



Entrance to location - Photo #03943



Wellheads - Photo #03944

Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SESE

Location ID: 335776

Date: 8/1/2024



Separators - Photo #03950



Tank battery/No tank battery sign - Photo #03952

Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SESE

Location ID: 335776

Date: 8/1/2024



Southwest corner of location - Photo #03971

Northwest corner of location - Photo #03972

Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SESE

Location ID: 335776

Date: 8/1/2024



Open to wildlife/hazard - Photo #03951



Open to wildlife/hazard - Photo #03956

Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SESE

Location ID: 335776

Date: 8/1/2024



Loose barbed wire/wildlife hazard - Photo #03961

Loose barbed wire/wildlife hazard - Photo #03963

Inspection Photos

Location: Caerus Piceance LLC Chevron/Texaco-66S97W/12SESE

Location ID: 335776

Date: 8/1/2024



Loose barbed wire/wildlife hazard - Photo #03965