

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2024

Submitted Date:

08/07/2024

Document Number:

713400220

FIELD INSPECTION FORM

Loc ID: 312649 Inspector Name: Popejoy, Dusty On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
ENERGY, VISION		mrine20@maralexinc.com	
ENERGY, VISION		pbechtolt@maralexinc.com	
ENERGY, VISION		mollieo@maralexinc.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222083	WELL	WO	12/20/1994	LO	077-08685	SULFUR GULCH 9-98-23 1	WO

General Comment:

[CECMC Inspection Report Summary](#)

On 7/30/2024 at approximately 10:33, Compliance Inspector Dusty Popejoy was on site to witness a Mechanical Integrity Test at VISION ENERGY LLC SULFUR GULCH 9-98-23-69S98W/23SWNW at Location ID #312649 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

Signs/Marker:

1- Sign lacks correct operator name, emergency contact and access road information. Spoke with Keegan O'Hare and he said he would provide the correct information for the sign with a CA date of 9/7/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

Location

Lease Road:

Type Access

comment: Access

Corrective ActionL

Date:

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: Sign lacks correct operator name, emergency contact and access road information. Spoke with Keegan O'Hare and he said he would provide the correct information for the sign, refer to photos.

Corrective Action: Comply with CECMC Signage rules.

Date: 09/07/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 222083 Type: WELL API Number: 077-08685 Status: WO Insp. Status: WO

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Operator didn't provide a Form 21 resulting in a failed MIT.
Last MIT -7/3/2018

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403880980	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6656142
713400221	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6656138