

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2024

Submitted Date:

08/15/2024

Document Number:

698602156

FIELD INSPECTION FORMLoc ID 411741 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------------------|---------|
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 291885 | WELL | PR | 09/07/2010 | GW | 125-10923 | ROUNDTREE 24-27 1N46W | PR |

General Comment:

Routine Inspection.

Location

| | | | |
|--------------------|--------------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track off maintained County Road | | |
| Corrective Action | L | Date: | |

Overall Good: ☐

| | | | |
|----------------------|--------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Well sign located at wellhead. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Emergency contact information posted on well sign. | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Stock panel fencing around surface equipment at well location. | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Post and Wire fencing. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Stock panel fencing around gas meter shed. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|------------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Dehydrator | # 1 | | |
| Comment: | Dehydrator on gas meter run inlet. | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Pump Jack welded steel pipe base. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Pump Jack Power and Control Panel. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|--|-------|
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Separator | # 0 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric Motor. | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | Gas Meter Shed. | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve open. Casing valve open. | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead plumbed to surface. | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Gas Meter Run. Chart in Meter Box dated 8-1-24. Meter Calibration/Test Log dated 5-30-24. Well Inlet Valve open. Gas Outlet Valve open. | | |
| Corrective Action: | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 291885 | Type: | WELL | API Number: | 125-10923 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Rods and tubing in wellbore. Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 6/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR. | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------|---|
| 698602200 | Inspection photos. | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666608 |