

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2024

Submitted Date:

08/12/2024

Document Number:

715200676

**FIELD INSPECTION FORM**Loc ID 321600 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 17180

Name of Operator: CITATION OIL &amp; GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207443	WELL	TA	01/23/2014	OW	017-06378	BLEDSON RANCH 14-30	PA

**General Comment:**[P&A Inspection](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Two track through pasture			
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Ancillary equipment	# 2			corrective date
Comment:	Electric panel and cathodic rectifier			
Corrective Action:	Remove equipment from location and begin final reclamation process			Date: 09/09/2024
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:	Remove equipment from location and begin final reclamation process			Date: 09/09/2024
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities											
Facility ID:	207443	Type:	WELL	API Number:	017-06378	Status:	TA	Insp. Status:	PA		
Cement											
Cement Contractor											
Contractor Name:					HP Oilfield Services					Contractor Phone:	
Surface Casing											
Cement Volume (sx):										Circulate to Surface:	
Cement Fall Back:										Top Job, 1" Volume:	
Intermediate Casing											
Cement Volume (sxs):										Good Return During Job:	
Production Casing											
Cement Volume (sx):										Good Return During Job:	
Plugging Operations											
Depth Plugs(feet range):					3050/2450/285					Cement Volume (sx):	180 SXS
Good Return During Job:					YES					Cement Type:	60/40 POZ
Comment:					HALDE WATER, CODELL WELL SERVICE, HP OILFIELD SERVICES. MIRU HP, PUMP 65SXS CMT THROUGH CICR @ 3050', W/5 SXS ON TOP @ 1500 PSI. MIRU CODELL, POOH TBG. RIH W/CICR TO 2450'. MIRU HP, PUMP 20 SXS CMT THROUGH CICR @ 2450' W/5 SXS ON TOP. MIRU CODELL, POOH W/TBG. MIRU HP, PUMP 45BBLS DOWN CSG TO BREAK CIRC, PUMP 85 SXS CMT DOWN CSG W/CMT TO SFC.						
Corrective Action:										Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403886241	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6662100">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6662100</a>