

# Inspection Photos

08/16/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335636

**Inspection Doc:** 696206134

Garfield County, CO

Aaron Trujillo  
Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 1:** Photos 1-2 taken from the east end of the working pad surface. Photos provide an overview of the Location from south, southwest, northwest to north.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 3:** Photos 3-4 examples showing stained soils observed around the wells and methanol tanks.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 4:** See comments under photo 3.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 5:** Photo shows open pipe observed along the north end of the well strings. This is a wildlife entrapment concern.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



August 16, 2024



August 16, 2024

**Photo 6:** Photos taken from the interim areas on the west end of the Location, facing south and north. Reclamation within these areas appears to be progressing towards 1003 Standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



August 16, 2024

**Photo 7:** Photo taken from the interim areas on the north end of the Location, facing west. Reclamation within these areas appears to be progressing towards 1003 Standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



August 16, 2024



August 16, 2024

**Photo 8:** Photos 8-9 taken from the interim areas on the east end of the Location. Photos examples showing stormwater runoff from the pad is resulting in degradation and sediment deposition within the interim areas; resulting in impacts to the reclamation as desirable perennial germination and establishment was not observed, or not uniform, within these areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 9:** See comments under photo 8.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 10:** Photos taken from the eastern perimeter of the Location. Photos examples showing BMPs have not been maintained, resulting in off-site sediment transport.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources