



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/16/2024
Submitted Date:
08/19/2024
Document Number:
696206138

FIELD INSPECTION FORM

Loc ID
311663

Inspector Name:
Trujillo, Aaron

On-Site Inspection ☐

2A Doc Num:

Operator Information:

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☒ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCInspectionReports@terraep.com	TEP
Toews, Wesley		wtoews@blm.gov	
Arthur, Denise		denise.arthur@state.co.us	
Smelser, Wayne		wayne.smelser@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
311663	LOCATION	AC			-	FEDERAL-66S94W 9SWSW	RI

General Comment:

On 8/16/2024, Reclamation Specialist Trujillo conducted an stormwater inspection at TEP Rocky Mountain LLC's FEDERAL-66S94W/9SWSW location in Garfield County, Colorado.

Location is Federal Surface and High Priority Habitat.

This inspection is a follow-up to #696205661 to document compliance with the following compliance issues:

-Stormwater / Surface disturbance minimization

It was observed in this inspection that corrective actions remain outstanding.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Date Run: 8/19/2024 Doc [#696206138]

Page 1 of 3

Inspected Facilities									
Facility ID:	311663	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696205661 observed that the access road leading south of the Location has not been constructed with a properly engineered stream crossing; vehicle tracking and degradation apparent at the crossing, impacting a riverine system and Waters of the State. Stream is a direct tributary to the Colorado river. Inspection required Operator to Comply with 1002 Rules.

It was observed in this inspection that BMPs, including a properly engineered stream crossing, has not been installed or maintained at the access road pursuant to Rules 1002.e and 1002.f. Degradation and tracking issues have persisted at the road/stream crossing.

Corrective actions per inspection #696205661 have not been addressed and remain applicable.

Corrective Action: Corrective action per inspection #696205661:
Comply with 1002 Rules.

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696206139	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6670856