

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2024

Submitted Date:

08/23/2024

Document Number:

715200755**FIELD INSPECTION FORM**Loc ID 324805 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 16520Name of Operator: CHEMCO INCAddress: 6970 SOUTH HOLLY CIR STE 206City: CENTENNIAL State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212776	WELL	SI	09/01/2018	GW	061-06136	T-WEAR 1	PA

General Comment:

Routine Inspection for OWP

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground and CRP		
Corrective Action		Date:	

Overall Good: ☒

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:		
Type	STORAGE OF SUPL	
Comment:	Tubing stored on east side of wellhead	
Corrective Action:		Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Heater Treater	# 1		
Comment:	Heated vertical gas separator next to dehydrator		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	North side of wellhead		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	North side of VGS		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical drum w/containment, overhead storage tank		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:	1-Vertical gas separator next to dehydrator 1-Vertical gas separator on north side dehydrator		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	1-Meter shed on south side of dehydrator 1-Meter shed west of HGS		
Corrective Action:		Date:	
Type: Dehydrator	# 1		

Comment:	West side of production tank		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		38.489580,-102.416980	
Comment:	Tank is empty at time of inspection					
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	212776	Type:	WELL	API Number:	061-06136	Status:	SI	Insp. Status:	PA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____									
<u>Comment:</u> Well had been plugged and abandoned. Wellhead has not been cut and capped. Well is in the process of transferring to OWP									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Well and location is located in farm ground

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200809	location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6680037