

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2024

Submitted Date:

08/26/2024

Document Number:

709100367

FIELD INSPECTION FORMLoc ID 433082 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10394

Name of Operator: CONDOR ENERGY TECHNOLOGY LLC

Address: 2203 TIMBERLOCH PLACE STE 128

City: THE WOODLANDS State: TX Zip: 77380

Status Summary:☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
I Yang		iyang@energycondor.com	
INGRISELLI, FRANK	925-263-2426	fingriselli@pedevco.com	PRESIDENT
Krystal Heibel		krystal.heibel@state.co.us	
,	281-377-5034	tdrew@pedevco.com	
Dylan Edwardson		dylan.edwardson@state.co.us	
Moore, Clark	(650) 888-1182	cmoore@pacificenergydevelopment.com	
Harper		harper@mienergy.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433071	WELL	PR	10/01/2020	OW	087-08172	Wickstrom 18 2H	EI
433082	LOCATION	AC			-	Wickstrom 18 1H	EI

General Comment:

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
Comment:	A Form 19 (Doc# 401242344) was submitted in March 2017 and the Form 19 Supplemental has not been submitted. This documents that the site investigation is not complete.			
Corrective Action:	Operator shall submit a Form 19 Supplemental and open a Form 27 Remediation Project for spills/releases that are not remediated within 90 days.			Date: 09/26/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	433071	Type:	WELL	API Number: 087-08172	Status:	PR	Insp. Status:	EI	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	433082	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									
Comment						User	Date		
This is a destop review of the Wickstrom 18 #1H (Location ID: 433082). A previous inspection (Doc# 709100144) tied the inspection to an abandonded well (API: 087-08174) instead of the location. This field inspection report correctly ties the past inspection to the location, instead of the abandonded well.						heibelk	08/26/2024		