

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2024

Submitted Date:

08/26/2024

Document Number:

713400259

FIELD INSPECTION FORM

 Loc ID 336045 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 16700
 Name of Operator: CHEVRON USA INC
 Address: 760 HORIZON DRIVE STE 401
 City: GRAND JUNCTION State: CO Zip: 81506
Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Aaron Katz		aaron.katz@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, CHEVRON		atlx@chevron.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291500	WELL	TA	12/01/2017	GW	045-14406	SKR 598-35-AV-10	TA

General Comment:[CECMC Inspection Report Summary](#)

On 8/16/2024 at approximately 11:17, Compliance Inspector Dusty Popejoy conducted an on-site inspection to observe a plugging operation on SKR 598-35-AV-10 well API# 05-045-14406 Document #403889224 at CHEVRON USA INC SKR-65S98W/35NWNE at Location ID #336045 in Garfield County, Colorado. At this time no plugging operations were observed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Any Corrective Actions from previous Inspections are still applicable.

Location

Lease Road:			
Type	Access		
comment:	Access.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	911/1-877-257-6007
Corrective Action:	
	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 291500 Type: WELL API Number: 045-14406 Status: TA Insp. Status: TA

Cement

Cement Contractor

Contractor Name: _____ Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: [Please refer to document #'s 403889196 & 403889224](#)
 8/16/2024 at 11:17 hours arrived on location to observe scheduled plugging operations. At this time no rig or plugging equipment were on location, spoke to a Chevron lease operator on location, he called someone that was over plugging operations and informed me that well SKR 598-35-AV-10 was plugged back in May of 2024 and were waiting to cut casing and remove wellhead until they were completed with all plugging operations. Documents show plugging operations starting on 8/16/2024 at 07:00 hours Spoke with Chevron consultant Dallas Russell 8/19/2024 and he confirmed P&A date was 5/11/2024

Corrective Action: **Contact engineering.** Date: 09/02/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400260	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6681561