

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad

Location #: 335688



Photo # 6357 From entrance to location




Photo # 6358 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad

Location #: 335688



Photo # 6359 Location



Photo # 6360 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad

Location #: 335688



Photo # 6361 Location



Photo # 6362 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad

Location #: 335688




Photo # 6363 Location



Photo # 6364 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad

Location #: 335688



Photo # 6365 Location



Photo # 6366 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad

Location #: 335688



Photo # 6367 Location



Photo # 6368 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad

Location #: 335688



Photo # 6369 Location



Photo # 6370 PRV vent line on tank burner does not comply with CECMC pressure safety device rules



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad

Location #: 335688



**Photo # 6371 Chemical tanks located in shed, shed is not labeled to indicate potential hazards inside.**



**Photo # 6372 Chemical tanks located in shed, shed is not labeled to indicate potential hazards inside.**