

Inspection Photos

August 21st, 2024

Operator: Seeley Oil Company - 10506

Location ID: 322118

Inspection Document #: 714001116

Dolores County, CO

Township: SESE 1 38N 20W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Southeast Spargo 1
Location ID: 322118



8/21/24
+37.578455,-108.996935
252° W



Photo 1. View of disturbance taken from the access point facing center.

Inspection Photos
Location Name: Southeast Spargo 1
Location ID: 322118



Photo 2. Produced water tank has been properly labeled with capacity.

Inspection Photos
Location Name: Southeast Spargo 1
Location ID: 322118



Photo 3. Guy line anchors on location have been properly marked.

Inspection Photos
Location Name: Southeast Spargo 1
Location ID: 322118



Photo 4. Weedy Russian thistle debris observed in a large patch at the produced water tank berm.

Inspection Photos
Location Name: Southeast Spargo 1
Location ID: 322118



Photo 5. Culvert at access point is starting to fill with sediment, future maintenance is advised.

Inspection Photos
Location Name: Southeast Spargo 1
Location ID: 322118



8/21/24
+37.578581,-108.996908
19° N



Photo 6. Reference area comprised of Brome snakeweed, Rabbirbrush, Juniper and Serviceberry.