

# Inspection Photos

Loc: 485654

Operator: BNL (ENTERPRISE) INC

Inspection Date: 8/26/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south toward the access road. The sides of the road will need to be reclaimed. The road has been regraded and crowned since previous inspection.





## Inspection Photos



**Photo 2.** The culvert outlet has been repaired and outlet protection was installed, The loose soil along the embankment need to be stabilized..



**Photo 3.** The embankment along the road side at the culvert is not stabilized and loose gravel is falling into the culvert.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Facing northwest toward the access road. The side of the road needs to be seeded and stabilized. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:485654 | Date: 8/26/2024

## Inspection Photos



**Photo 4.** Facing west toward the location. Sign posted at entrance.





## Inspection Photos



**Photo 5.** Facing southwest at the location. The silt fence is not maintained.





## Inspection Photos



**Photo 6.** Facing toward the soil stock pile. The topsoil has not been seeded and stabilized and there are weeds established along the topsoil.





## Inspection Photos



**Photo 7.** Facing toward the west corner of the location. The silt fence still remain down in this area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:485654 | Date: 8/26/2024



## Inspection Photos



**Photo 8.** Facing southeast along the fill slope. There is erosion occurring shown at red arrow.

