

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2024

Submitted Date:

08/25/2024

Document Number:

695110170

FIELD INSPECTION FORMLoc ID 322107 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10754

Name of Operator: FOUR CORNERS ENERGY LLC

Address: 500 DALLAS STREET #1650

City: HOUSTON State: TX Zip: 77002

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,		JFulcher@bwenergyllaw.com	
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
,		rhankins@americanhelium.us	
,		irobets@americanhelium.us	
Demarco, Jaime		jdemarco@blm.gov	
,		dnr_ecmc_engineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208980	WELL	SI	10/01/2017	GW	033-06085	WILLIE WASCHKE 4-17	SI

General Comment:

ECMC staff performed a field inspection on 08/25/2024.

Issues were found requiring corrective action. See inspection text and photos for details.

Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location					
Lease Road:					
Type	Access				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	OTHER				
Comment:	PHOTO 1: WELL SIGN/ COMPANY NAME POST ON LOCATION IS INACCURATE AND EMERGENCY CONTACT NUMBERS ARE INVALID.				
Corrective Action:	UPDATE EMERGENCY CONTACT PHONE NUMBER AS SOON AS POSSIBLE AND POST CURRENT OPERATOR NAME PER RULE 605.				Date: 10/26/2024
Emergency Contact Number:					
Comment:					
Corrective Action:					Date: _____
Good Housekeeping:					
Type	WEEDS				
Comment:	PHOTO 2, 4, 5 & 6: LOCATION/ WEED MAINTANANCE NEEDED THROUGHOUT THE LOCATION INSITER BURMS FOR TANK BATTERY AND HEATED SEPARATOR.				
Corrective Action:	MAINTAIN WEEDS THROUGHOUT LOCATION AND REMOVE ALL WEEDS INSIDE TANK BATTERY BURMS, Comply with Rule 603.f				Date: 09/05/2024
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Deadman # & Marked	# 4				corrective date
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:	Last cal. report was in July 2016				
Corrective Action:	PROVIDE AREA FIELD INSPECTOR (@ tom.beardslee@state.co.us & steve.labowskie@state.co.us) A COPY OF THE GAS METER CALIBRATION RECORD OR KEEP A COPY OF LAST CALIBRATION RECORD ON LOCATION.				Date: 09/05/2024
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		37.636579,-104.962545	
Comment:	See photo of tank color/condition. Production facility is clearly visible from a public highway, road, or publicly-maintained trail. Facility paint is not uniform, non					
Corrective Action:	Comply with rukle 425. CA adjusted for seasonal conditrions, previous operator cited for same issue. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.					Date:

Paint

Condition	Inadequate	
Other (Content)	FLIR CAMARA INDICATES FLUID LEVEL IS APPROX. 6'	
Other (Capacity)	400 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	SEE HOUSE KEEPING SECTION FOR CORRECTIVE ACTION ON WEEDS ON AND INSIDE BERMS				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	208980	Type:	WELL	API Number:	033-06085	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:			
Comment:		<div>Well shut in 8/2016. No MIT on record. Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.</div>							
Corrective Action:		<div>Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208. This is the second notice for this corrective action, immediate action is required.</div>					Date:		
BradenHead									
Date of Last Brhd Test:		12/12/2023		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		10		Fluid Type:		NONE	
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: weeds on row need maintained.

Corrective Action: maintain weeds on row per rule 606.

Date: 09/06/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695110184	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684491