

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2024

Submitted Date:

08/26/2024

Document Number:

695110182**FIELD INSPECTION FORM**Loc ID 322089 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10754Name of Operator: FOUR CORNERS ENERGY LLCAddress: 500 DALLAS STREET #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		JFulcher@bwenergyllaw.com	
Labowskie, Steve		steve.labowskie@state.co.us	
		dgavito@americanhelium.us	
		jroberts@americanhelium.us	
Demarco, Jaime		jdemarco@blm.gov	
		rhankins@americanhelium.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208904	WELL	PR	01/01/2021	GW	033-06008	HUSKEY "B" UNIT 1	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	PHOTO 1: WELL SIGN/ COMPANY NAME POST ON LOCATION IS INACCURATE AND EMERGENCY CONTACT NUMBERS ARE INVALID.		
Corrective Action:	UPDATE EMERGENCY CONTACT PHONE NUMBER AS SOON AS POSSIBLE AND POST CURRENT OPERATOR NAME PER RULE 605.	Date:	10/26/2024

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	PHOTO 8 & 9: WEEDS NOT MAINTAINED ON AND INSIDE CRUDE OIL TANK BATTERY SECONDARY CONTAINMENT BERMS. PHOTO 10: WEEDS NOT MAINTAINED ON AND INSIDE PRODUCED WATER BATTERY SECONDARY CONTAINMENT BERMS.		
Corrective Action:	REMOVE WEEDS INCLUDING ON ALL SECONDARY CONTAINMENT BERMS PER RULE 606.	Date:	09/07/2024
Type	WEEDS		
Comment:	PHOTO 6: WEEDS NOT MAINTAINED AROUND LOCATION. PHOTO 7: WEEDS NOT MAINTAINED AROUND PUMPJACK.		
Corrective Action:	MAINTAIN WEEDS AROUND LOCATION PER RULE 606.	Date:	09/07/2024
Type	OTHER		
Comment:	PHOTO 11 & 12: AREA ON IMPACTED SOIL NEAR PUMPJACK PRIME MOVER APPEARS TO BE FROM LEAKING PRIME MOVER.		
Corrective Action:	REPAIR EQUIPMENT, INCREASE Self-inspection, maintenance, and good housekeeping procedures and schedules PER RULE 1002..(2).D.	Date:	09/07/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	IS ACCESSABLE	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		37.611923,-104.993708
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	210 BBL
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		37.612375,-104.993587
Comment:	PHOTO 13: TANK IS VENTING FROM NEAR HATCH SEE ATTACHED FLIR VIDEO.				
Corrective Action:	Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9).				Date: 08/28/2024

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	465 BBL
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:			
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	208904	Type:	WELL	API Number:	033-06008	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:					Date:				
BradenHead									
Date of Last Brhd Test:		12/12/2023		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type: NONE			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #700300286, THE CA FOR EMERGENCY CONTACT HAS NOT BEEN ADDRESSED, THE CA FOR METER CALIBRATION REPORT HAS BEEN ADDRESSED.	beardslt	08/26/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695110198	FLIR VIDEO	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684496">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684496</a>