

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	PHOTO 1: WELL SIGN/ COMPANY NAME POST ON LOCATION IS INACCURATE AND EMERGENCY CONTACT NUMBERS ARE INVALID.		
Corrective Action:	UPDATE EMERGENCY CONTACT PHONE NUMBER AS SOON AS POSSIBLE AND POST CURRENT OPERATOR NAME PER RULE 605.	Date:	10/27/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 9: UNUSED EQUIPMENT THE WELLHEAD (1" RISER NEAR WELLHEAD). PHOTO 10: UNUSED EQUIPMENT TO THE WEST OF CRUDE OIL TANK BATTERY (2 -3" RISERS AND 1-2" RISERS).		
Corrective Action:	REMOVE UNUSED RISERS PER RULE 606.	Date:	09/27/2024
Type	WEEDS		
Comment:	PHOTO 2,3,5,7,8 & 9: WEEDS HAVE NOT BEEN MAINTAINED THROUGHOUT LOCATION.		
Corrective Action:	MAINTAIN WEEDS PER RULE 606.	Date:	09/07/2024

Overall Good:

Spills:

Type	Area	Volume			
In Containment: No					
Comment: <input style="width: 80%;" type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					

Equipment:

				corrective date
Type: Bradenhead	# 1			
Comment:				
Corrective Action:			Date:	
Type: Other	#			
Comment:	WELLHEAD/ PACKING IS LEAKING GAS FROM WELL, SEE ATTACHED FLIR VIDEO.			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date:	09/13/2024
Type: Deadman # & Marked	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	

CRUDE OIL	3	400 BBLs	STEEL AST		37.654567,-104.986198
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: NOTE: THE LINER IS UNCOVERED IN SOME AREAS, LINER SHOULD BE COVERED TO ENSURE LINER INTEGRATY.					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 432376 Type: WELL API Number: 033-06174 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: WELL HAS BEEN SHUT IN SINCE OCT. 2015 AND HAS NO MIT'S ON FILE

Corrective Action: Submitted Form 21, or Form 6 must be approved by the corrective action date for any wellbore not demonstrating current mechanical integrity. Wells demonstrating mechanical integrity must accomplish production without the use of mechanical intervention per rule 417.b. 10 day notice via form 42 is required for all MIT's.

Date: 09/07/2024

BradenHead

Date of Last Brhd Test: 12/12/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Ditches	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695110203	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684501
695110204	FLIR VIDEO	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684502