


Operator: 8 North

Location Name: RANCH-611N61W 18NWNW

Loc ID: 317622

Inspection: 684905110



CA: Stained soil at engine, exhaust: Comply with rule 603.f

CA Resolution: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed to comply with the 600 and 900 series.