

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2024

Submitted Date:

08/29/2024

Document Number:

707603150

FIELD INSPECTION FORMLoc ID: 427120 Inspector Name: Evins, Bret On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427119	WELL	SI	02/01/2023	OW	123-34874	SCHAEFER 10J-203	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID
(427120).
(Well(s): 4: Shut-In | SI).

Centralized Battery serves 1 Tank Battery Facility ID
(Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707603148 and/or Location ID #427120
for SI Well(s), Corrective Action (CA) info.
B.) Field Inspection Report doc. #707603150 and/or Location ID #427120
for SI Well(s), Corrective Action (CA) info.
C.) Field Inspection Report doc. #707603152 and/or Location ID #427120
for SI Well(s) info.
D.) Field Inspection Report doc. #707603154 and/or Location ID #427120
for SI Well(s) info.
E.) Field Inspection Report doc. #707603156 and/or Location ID #427120
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Wellsite: Paraffin Control. Placards.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel, barbed wire.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellsite: 1: Paraffin Control pump, tank w/ drip containment. Placards.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.507655,-104.428029	
Comment:	Centralized Battery serves 1 Location ID (427120). (Well(s): 4: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 427119 Type: WELL API Number: 123-34874 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.
ECMC records last prod: 01/2023.
Form 5B on file. Defined Inactive date: 01/31/2023. Approved.
Locked-Out, Tagged-Out | LOTO.
OOSLAT at well, separator: 08/08/2024.

CORRECTIVE ACTION: see below.

Corrective Action: 1.) Well GPS coordinates are inaccurate per Form 5 Final Drilling Completion Report.
See Doc. #400327627 dated: 10/18/2012.
Refer to Rule 414.b.(2).F for guidance.
* Collect updated / accurate GPS coordinates at wellsite to comply with Rule 414.b.(2).F.
& Rule 216. Report updated / accurate GPS coordinates on ECMC Form 4 Sundry
Notice,
Section "CHANGE OF LOCATION OR AS BUILT GPS REPORT."
Corrective Action date: 09/30/2024.
See photo #2.
* A follow up on this site inspection will be conducted to ensure that compliance issues
have been corrected to comply with ECMC rules.

Date: 09/30/2024**BradenHead**Date of Last Brhd Test: 04/30/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On TUE 08/27/2024 at approximately 13:49 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: Schaefer/NW-10 Pad Location ID: 427120 Well Name(s): Schaefer 10J-203. API: 123-34874. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>During this inspection the following possible compliance issue(s) were observed: 1.) Well GPS coordinates are inaccurate per Form 5 Final Drilling Completion Report. See Doc. #400326858 dated: 10/18/2012. Refer to Rule 414.b.(2).F for guidance. * Collect updated / accurate GPS coordinates at wellsite to comply with Rule 414.b.(2).F. & Rule 216. Report updated / accurate GPS coordinates on ECMC Form 4 Sundry Notice, Section "CHANGE OF LOCATION OR AS BUILT GPS REPORT." Corrective Action date: 09/30/2024. See photo #2.</p> <p>* A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with ECMC rules.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/29/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603151	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688580