

# Interim Reclamation and Stormwater Inspection

Date: 8/21/24

Operator: Crestone Peak Resources Operating LLC -  
10633

Location ID: 449179

Inspection Document #: 713900906

Adams County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Bear 3-65 22-23  
Location ID: 449179



**Photo 1.** The photo was taken at the well location facing Southwest. The photo illustrates an overview of the well location.



**Photo 2.** The photo was taken at the well location facing Northeast. The photo illustrates interim areas are vegetated and being managed with evidence of mowing as well as the location sediment trap.



Inspection Photos  
Location Name: Bear 3-65 22-23  
Location ID: 449179



**Photo 3.** The photo was taken at the well location facing Northwest. The photo illustrates the entrance and topsoil stockpile. The stockpile at the time of inspection was vegetated and mowed.



**Photo 4.** The photo was taken at the well location facing West. The photo illustrates the stabilized culvert at the entrance to well location.

Note - Wattle around outlet needs replaced.



Inspection Photos  
Location Name: Bear 3-65 22-23  
Location ID: 449179



**Photo 5.** The photo was taken at the well location facing South. The photo illustrates the western topsoil stockpile is vegetated and mowed.



**Photo 6.** The photo was taken at the well location facing West. The photo illustrates wildlife screen on exhaust pipe needs replaced.



Inspection Photos  
Location Name: Bear 3-65 22-23  
Location ID: 449179



**Photo 7.** The photo was taken at the well location facing Southwest. The photo illustrates wildlife protections on secondary containment are not secured.



Inspection Photos  
Location Name: Bear 3-65 22-23  
Location ID: 449179



**Photo 8.** The photo was taken at the well location facing South. The photo illustrates that there has been a wildlife mortality (appeared to be a Red-winged blackbird) inside secondary containment due to wildlife protections not being secured.



Inspection Photos  
Location Name: Bear 3-65 22-23  
Location ID: 449179



**Photo 9.** The photo was taken at the well location facing South. The photo illustrates the netting around the secondary containment of a tank has not been installed correctly, not extending over the edge of the tank, and could lead to more wildlife mortality.