

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 18-10 (J18) Pad

Location #: 334865



Photo # 7478 From Entrance to location



Photo # 7479 From Entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 18-10 (J18) Pad

Location #: 334865




Photo # 7480 Location



Photo # 7481 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 18-10 (J18) Pad

Location #: 334865



Photo # 7482 Location



Photo # 7483 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 18-10 (J18) Pad

Location #: 334865



Photo # 7484 Location



Photo # 7485 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 18-10 (J18) Pad

Location #: 334865



Photo # 7486 Rupture disc vent line does not comply with CECMC pressure safety device rules




Photo # 7487 Rupture disc vent line does not comply with CECMC pressure safety device rules