

Inspection Photos

Location Name: CAERUS PICEANCE LLC Shideler Fee 31-13C (O31E) Pad

Location #: 334156



Photo # 7021 From Entrance to location



Photo # 7022 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC Shideler Fee 31-13C (O31E) Pad

Location #: 334156



Photo # 7023 Location



Photo # 7024 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC Shideler Fee 31-13C (O31E) Pad

Location #: 334156



Photo # 7025 Location



Photo # 7026 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Shideler Fee 31-13C (O31E) Pad

Location #: 334156




Photo # 7027 Location



Photo # 7028 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC Shideler Fee 31-13C (O31E) Pad

Location #: 334156




Photo # 7029 Location



Photo # 7030 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC Shideler Fee 31-13C (O31E) Pad

Location #: 334156



Photo # 7031 Open pipe/wildlife hazard



Photo # 7032 Open pipe/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC Shideler Fee 31-13C (O31E) Pad

Location #: 334156



Photo # 7033 Flowline heating insulation open ended/open to entry by wildlife/wildlife hazard



Photo # 7034 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC Shideler Fee 31-13C (O31E) Pad

Location #: 334156



Photo # 7035 Secondary containment liner needs maintenance



Photo # 7036 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC Shideler Fee 31-13C (O31E) Pad

Location #: 334156



Photo # 7037 Debris