

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2024

Submitted Date:

09/02/2024

Document Number:

708302666

**FIELD INSPECTION FORM**Loc ID 334656 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287314	WELL	PR	11/01/2021	GW	045-12962	SHORE 16-10 (PJ16)	PR
287994	WELL	PR	12/01/2021	GW	045-13126	SHORE 16-11BB(PJ16)	PR
287995	WELL	PR	12/01/2021	GW	045-13125	SHORE FEDERAL 16-14 (PJ16)	PR
287996	WELL	PR	11/01/2021	GW	045-13124	SHORE 16-11(PJ16)	PR
288990	WELL	PR	11/01/2021	GW	045-13628	SHORE 16-10BB (PJ16)	PR
289666	WELL	PR	11/01/2021	GW	045-13846	SHORE FEDERAL 16-15BB (PJ16)	PR
289667	WELL	PR	12/01/2021	GW	045-13845	SHORE FEDERAL 16-15 (PJ16)	PR

**General Comment:****CECMC Inspection Report Summary**

On 8/28/2024 at approximately 13:25, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE at Location ID #334656 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Stored supplies on location

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970)285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Cattle panels stored on southwest end of location.		
Corrective Action:	Remove stored supplies from location to comply with Rule 606.		Date: 09/09/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

**Equipment:**

Type: Horizontal Heated Separator	# 7		corrective date
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Generator and trailer		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 287314	Type: WELL	API Number: 045-12962	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 287994	Type: WELL	API Number: 045-13126	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 287995	Type: WELL	API Number: 045-13125	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 287996	Type: WELL	API Number: 045-13124	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 288990	Type: WELL	API Number: 045-13628	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 289666	Type: WELL	API Number: 045-13846	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 289667	Type: WELL	API Number: 045-13845	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
				Material Handling And Spill Prevention		
Berms						
		Compaction				
Compaction						
Gravel						
		Gravel				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302667	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6690521">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6690521</a>