

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Photo # 6748 From entrance to location




Photo # 6749 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Photo # 6750 Location



Photo # 6751 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Photo # 6752 Location



Photo # 6753 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Photo # 6754 Location



Photo # 6755 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Aug 27, 2024 at 12:39:52 PM
CO

Photo # 6756 Location



Aug 27, 2024 at 12:47:25 PM

Photo # 6757 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Photo # 6758 Location



Photo # 6759 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Photo # 6760 Debris



Photo # 6761 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Photo # 6762 Tank battery lacks required signage



Photo # 6763 Unused equipment on location (labels on unused chemical tank are also illegible)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Photo # 6764 Tank lacks capacity



Photo # 6765 Multiple PRV vent lines do not comply with CECMC pressure safety device rules



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE 43-33H Pad

Location ID: 334690



Photo # 6766 Multiple PRV vent lines do not comply with CECMC pressure safety device rules

