

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2024

Submitted Date:

08/30/2024

Document Number:

713301092

**FIELD INSPECTION FORM**Loc ID 317708 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239827	WELL	SI	05/01/2024	OW	123-07615	COSSLETT 1	SI

**General Comment:**

well site follow up inspection

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	both well head signs, wrong API #'s and sec/ts/rng, photos 3 & 4		
Corrective Action:	Comply with Rule 605d	Date:	01/05/2024

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 3		corrective date
Comment:	automation/electric panels		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 239827

Type: WELL

API Number: 123-07615

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/06/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>Audit of scout card and related documents</div> <div>Follow up inspection as per Doc # 713300345, corrective actions appeared to have not been addressed, Both new sign on site have wrong API number Sign not posted or information inaccurate</div> <div>ECMC Inspection Report Summary</div> <div>Location: Cosslett 1 Operator: KPK API#: 123-07615 County: Weld While there, I observed well site with pumping unit During this inspection the following possible compliance issues were observed: Sign, Rule 605d, corrective action date 1-5-2024</div> <div>Weather conditions: sunny and dry</div> <div>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</div> <div>This inspection does not nullify any orders or NOAV from the ECMC</div>	kestern	08/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301093	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6690720">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6690720</a>