

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2024

Submitted Date:

09/03/2024

Document Number:

715200846

## FIELD INSPECTION FORM

Loc ID 326557 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

23 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General	970-749-4139	sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257165	WELL	PR	10/30/2000	CBM	067-08296	LUDWIG 2	PR

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access location from intersection of Kremer Dr and Star Crossing		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by gate at entrance		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Stickers on chemical tank		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank. Stickers on separator and meter shed are faded and need replaced		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds around location inside fence need to be maintained. Tall weeds on south side of location		
Corrective Action:	Comply with Rule 606	Date:	09/29/2024
Type	STORAGE OF SUPL		
Comment:	Trailers, snow plows and drags stored on west side of location		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Metal panels around telemetry equipment		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Metal panels around separator, meter shed and pig station		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Metal panels around buried water tank		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Chain link privacy fence with green slats		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead. Metal cage around gear box		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Lufkin 160		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Bird protector on separator stack		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Electric panels, phase convertor, telemetry on northwest corner of location, chemical tank on south side of wellhead		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter shed on east side of separator. Calibration shows 1/9/24		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	Launching station on south side of separator		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:	Vertical heated separator on east side of water tank		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	BV STEEL		37.233640,-107.583200	
Comment:	21bbl buried steel water tank on north side of location					
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	21bbls				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Date Run: 9/3/2024 Doc [#715200846]

Page 4 of 6

Inspected Facilities									
Facility ID:	257165	Type:	WELL	API Number:	067-08296	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Well is PR at time of inspection							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		06/05/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		4		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass			Material Handling And Spill Prevention	Pass	
Rip Rap	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200878	location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691886">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691886</a>