


**Operator: 8 North**

**Location Name: EVERITT-611N61W 14NWSW**

**Loc ID: 302935**

**Inspection: 696300869**









**CA:** Unused Wellhead Parts, see photo 4. Comply with Rule 603.f .

**CA Resolution:** Unused equipment has been removed from the location to comply with the 600 series.

**CA:** Stained Soil at Gas Engine, see photo 3. Properly treat or dispose of oily waste in accordance with 907.e.

**CA Resolution:** Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.