

Inspection Photos
Location: Reynard 34-34
Location ID: 333697
API # 05-071-07092



Photo 1 –Well placard on meter house.



Photo 2 – Wellhead and equipment.

Inspection Photos
Location: Reynard 34-34
Location ID: 333697
API # 05-071-07092



Photo 3 – Pit Facility ID 260821



Photo 4 – Pit Flowline not in use.

Inspection Photos
Location: Reynard 34-34
Location ID: 333697
API # 05-071-07092



Photo 5 – Oil Stained soils at engine skid



Photo 5 – Oil stained soils on well pad

Inspection Photos
Location: Reynard 34-34
Location ID: 333697
API # 05-071-07092



Photo 7 – Stormwater is causing erosion at road intersection

