

Operator: 8 North

Location Name: DF RANCH-611N61W 2SWSW

Loc ID: 410183

Inspection: 696300965







CA: Stained Soil at Exhaust and Wellhead, see photos 2 and 3. Properly treat or dispose of oily waste in accordance with 907.e

CA Resolution: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.